

ALTERNATOR AND GENERATOR
 ALTERNATEUR ET DYNAMO
 DREHSTROM-WECHSELSTROM-LICHTMASCHINE
 ALTERNATORE E GENERATORE
 ALTERNADOR Y DINAMO

PLATE D
 PLAQUE D
 PLATTE D
 PIASTRA D
 PLACA D

(A) NO LONGER REQUIRED. USE SCREWS 2163745, WASHER 0920052 AND DELETE TWO NUTS 2168519.
 PLUS NECESSAIRE - UTILISER VIS 2163745, RONDELLE 0920052 ET SUPPRIMER 2 EROUS 2168519
 A NON PIU' RICHIESTO - USARE VITI 2163745, ROSETTE 0920052 E TOGLIERE I DUE DADI 2168519
 YA NO SE NECESITA - USE TORNILLOS 2163745, ARANDELA 0920052 Y SUPRIME 2 TUERCAS 2168519

(B) 4 - REQUIRED ONLY WHEN INSULATING STRIP IS FITTED 2 - REQUIRED WHEN INSULATING STRIP IS NOT FITTED.
 4 NECESSAIRES SEULEMENT SI UNE BANDE ISOLANTE EST MONTÉE 2 NECESSAIRES SI BANDE ISOLANTE PAS MONTÉE
 4 RICHIESTI QUANDO E' MONTATO IL GIUNTO ISOLANTE 2 RICHIESTI QUANDO IL GIUNTO ISOLANTE NON E' MONTATO
 SE NECESITAN 4 SOLO QUANDO SE MONTA CINTA AISLADORA SE NECESITAN 2 CUANDO NO SE MONTA CINTA AISLADOR

89350 NDHB-001-D

